ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

**Zone**
YELAHANKA

**Ward No.**
8

**Ward Name**
Kodigehalli

**Street ID**
W0447, W0388

**Street Name**
Shetty Lyt, 3rd Main Rd, Doddamuniswammppa Lyt, 3rd Crs

**Significant Landmark**
Tatanagara

**Segment No.**
8/C-W0447/S061417

**Total Length (m)**
168.61

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 168.61 | 77.573374 | 13.054503 | 77.573877 | 13.055945 | Tatanagara | 4th main |

### Work Details

**History of Road / Lane / Circles**

**Name of the Work**
Improvements to drains in 1st to 4th main road, 2nd Cross road to 8th cross road in Tatanagara in ward no. 08, Kodigehalli.

**Sanctioned Estimated Amount (Rs.)**
2000000

**Sanctioned Year**
2015-16

**Year**
2015 - 2016

**Type of Work**
Others

**Other Work Type**
Providing granints Slabs

**Tender**
Tender

**Work Details**

**Job No. / Work Code**
008-16-000019

**Work Order No.**
BBMP/EE/BTP/WO/70/2015-16

**Work Order Date**

**Period of Extention**

**Defect Liability Period From**
21/04/2017

**Defect Liability Period To**
21/04/2018

**Multiple road involved with the same Job No/ Work Code #**
No

### Contractor Details

**Name of Contractor**
Narasimhaiah N

**Contractor Reg No (BBMP/PWD)**

**Expenditure Booked \ Released (Rs)**
0.00

**Phone No.**
9343197369

**E-Mail ID**

## Field Inspection Details

**Number of Trees**

1

**Any Other Information**

**Name**

dhanjaya

**Date of Inspection**

30/05/2017

**Remarks**

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition |  | This photo seems out of range. |
| Drain Condition |  | This photo seems out of range. |
| Segment Start |  | This photo seems out of range. |
| Segment Start |  | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | Parameshwaraiah | 30/05/2017 | 28/06/2017 | Approved |
| SE | K.M. Vasu | 30/05/2017 | 28/06/2017 | Verified |
| EE | Mohan das | 30/05/2017 | 28/06/2017 | Verified |
| AEE | Ranganath | 30/05/2017 | 28/06/2017 | Verified |
| AE | Dhanjaya | 30/05/2017 | 28/06/2017 | Mobile verification done |
| AE | Dhananjaya | 29/05/2017 | 28/06/2017 | Forwarded |

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

**Zone**
YELAHANKA

**Ward No.**
8

**Ward Name**
Kodigehalli

**Street ID**
W0388, W0449

**Street Name**
Doddamuniswammppa Lyt, 3rd Crs

**Significant Landmark**
Tatanagara

**Segment No.**
8/C-W0388/S055019

**Total Length (m)**
120.40

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 120.40 | 77.573728 | 13.054402 | 77.574055 | 13.055442 | Tatanagara | 3rd Cross |

### Work Details

**History of Road / Lane / Circles**

**Name of the Work**
Improvements to drains in 1st to 4th main road, 2nd Cross road to 8th cross road in Tatanagara in ward no. 08, Kodigehalli.

**Sanctioned Estimated Amount (Rs.)**
2000000

**Sanctioned Year**
2015-16

**Year**
2015 - 2016

**Type of Work**
Others

**Other Work Type**
Providing granite slabs drain

**Tender**
Tender

**Work Details**

**Job No. / Work Code**
008-16-000019

**Work Order No.**
BBMP/EE/BTP/WO/70/2015-16

**Work Order Date**

**Period of Extention**

**Defect Liability Period From**
28/04/2017

**Defect Liability Period To**
28/04/2018

**Multiple road involved with the same Job No/ Work Code #**
No

### Contractor Details

**Name of Contractor**
Narasimhaiah N

**Contractor Reg No (BBMP/PWD)**

**Expenditure Booked \ Released (Rs)**
0.00

**Phone No.**
9343197369

**E-Mail ID**

## Field Inspection Details

**Number of Trees**

3

**Any Other Information**

**Name**

dhananjaya

**Date of Inspection**

30/05/2017

**Remarks**

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition |  | This photo seems out of range. |
| Drain Condition |  | This photo seems out of range. |
| Drain Condition |  | This photo seems out of range. |
| Segment Start |  | This photo seems out of range. |
| Segment Start |  | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | Parameshwaraiah | 30/05/2017 | 29/06/2017 | Approved |
| SE | K.M. Vasu | 30/05/2017 | 29/06/2017 | Verified |
| EE | Mohan das | 30/05/2017 | 29/06/2017 | Verified |
| AEE | Ranganath | 30/05/2017 | 02/07/2017 | Verified |
| AE | Dhanjaya | 30/05/2017 | 28/06/2017 | Mobile verification done |
| AE | Dhananjaya | 29/05/2017 | 28/06/2017 | Forwarded |